STONHARD SPOTLIGHT

STONHARD PROVIDES ULTRA-DURABLE, HYGIENIC FLOOR AND WALL SOLUTIONS FOR PHARMACEUTICAL COMPANY



Problem: Renovation caused imperfections in concrete and customer needed a hygienic solution at the walls

Product Solution: Stonshield®HRI with Stonseal®CA7 and Polysto®OP20F

Scope of work: Fill suite and support rooms

Stonhard knows that pharmaceutical require high-performing, snaces innovative solutions to keep their operations running smoothly and safely. When a global pharmaceutical company was making renovations on their Texas facility's fill suite and support rooms, they came to Stonhard to solve their problems and ensure an effective, longterm solution. During the renovation of the fill suite, all the walls were removed, and patching was required where the walls once stood. Stonhard applied a quarter inch mortar base to level out imperfections in the concrete and the different elevations between old rooms

and walls. Stonshield®HRI was chosen by the customer for its decorative quartz aggregate, durability, and chemical and stain resistance.

In addition to a flooring system, the customer was looking for an alternative to the stainless-steel bumper rails they had used to protect walls from damage by carts. Cleaning behind these rails was difficult. Stonhard, the exclusive turnkey partner of Polysto® in the United States, installed OP20F, a prefabricated, exceptionally durable, water-resistant curb system that provides sanitary design, a seamless transition from floor to wall, and a system that is much easier to clean.

